Landscape Plan Implementation Reference Materials

The following information from the Slope Stability Assessment report is included for reference when implementing the strategies for Objective 1, which states "Ensure no significant risk to public health, safety and resources, and tribal archaeological and cultural resources from forest management related mass-wasting events.

Slope Stability Sensitive Area Map

A Slope Stability Sensitive Area Map was developed for the Planning Area. It is intended to include both unstable slopes and potentially unstable slopes. The map is a composite of: 1) high and moderate slope stability hazard areas identified by the Lake Whatcom and Acme Watershed Analysis reports; 2) adjustments to portions of the high hazard slope stability map created by Watershed Analysis reports based on aerial photo interpretation, slope gradients indicated on DNR topographic map, or personal knowledge of local conditions; 3) slopes indicated to be steeper than 70% on the DNR topographic map; and 4) high slope stability hazard areas mapped as part of this Assessment in the Cain Lake basin and on the west side of Lookout Mountain.

The Slope Stability Sensitive Area Map is a compilation of the best available information regarding slope stability conditions on the Planning Area. Its level of accuracy is reasonable and sufficient for planning purposes. However, the map no doubt contains errors of inclusion and exclusion. That is, the specific locations of stable, potentially unstable, and unstable slopes are probably not represented entirely accurately on the map. For this reason, the <u>definitions</u> of unstable and potentially unstable slopes (as opposed to map locations) are the determining criteria for field identification.

Definitions of Unstable Slopes and Potentially Unstable Slopes

The attempt to distinguish between unstable slopes and potentially unstable slopes was undertaken because legislation (Engrossed Second Substitute Senate Bill 6731) directing this planning effort implies that there is a difference, and different management practices are prescribed. In fact, it is not always possible to distinguish between unstable slopes and potentially unstable slopes. (The full range of possible slope stability conditions is best envisioned as a continuum rather than a series of discrete pigeonholes.) Positive identification of potentially unstable slopes is often difficult because past slope stability conditions may not accurately foretell future conditions. Slope stability determinations are subjective processes involving the application of both "science" and professional judgment.

Unstable slopes exhibit evidence of recent (up to decades) persistent or sporadic mass movement. Instability may be related to, or independent of, forest management activities.

Potentially unstable slopes are:

- Over-steepened areas (critical gradient varies with site conditions)
- Inner gorges
- Convergent headwalls
- Bedrock hollows >70%

Appendix G

- Toes and scarps (>65% of deep-seated landslides
- Valley walls at outer edges of stream meanders
- Areas that exhibit a combination of "indicators" which, when considered cumulatively, indicate potential for landsliding

Potentially unstable slopes do not exhibit evidence of recent landsliding.


Example "Indicators" or Landslide Potential

- New or abandoned stream channels; channels angled across slope
- Sag ponds
- Wet slopes showing springs, groundwater seepage, wet-site vegetation
- Linear, arcuate or other patterns of disturbed vegetation
- Jack-strawed, pistol-butted, tilted, or split trees
- Old landslide scars
- Very steep slopes
- Ground surface tension cracks' small scarps (cat-steps)
- Hummocky ground
- Cracked, sagged, slumped roadways
- Debris piled against uphill side of trees
- Freshly exposed bedrock surfaces or cracks

Application of Slope Stability Assessment Information

Proposed management activities within areas delineated on the Slope Stability Sensitive Area Map should be reviewed by a slope stability specialist. The specialist should first determine whether the proposed activity involves, or likely could affect, unstable or potentially unstable slopes. The <u>definition</u> of unstable and potentially unstable slopes – as opposed to map location – is the determining criteria for field identification.) If unstable or potentially unstable slopes are present, the likely effects of the proposed activity need to be specifically identified. Both site-specific slope stability-related conditions and details of the proposed activity need to be considered in determining its likely effects, and whether (or to what degree) the effects can be mitigated. These decisions should be made through an interactive process involving the sloe stability specialist, the timber harvest engineer and/or road engineer, and other appropriate specialists.

The Slope Stability Sensitive Area Map and the slope stability evaluation procedures suggested in this Assessment do <u>not</u> supersede existing Watershed Analysis reports covering the Lake Whatcom Landscape Planning Area. Proposed management activities in the Planning Area will continue to be regulated by Forest Practices Rules and applicable Watershed Analysis Prescriptions.





December 08, 2003 J. Stuart

MWMU 1B (ARS 1) - Moderate Headscarps and toes of ancient and dormant deep-seated landslides

MWMU 1C (ARS 2) - High Incised stream channels within deep-seated landslides

MWMU 2 (ARS 3) - High Incised stream channels and associated landforms in Darrington Phyllite


MWMU 4 (ARS 4) - High Incised stream channels and associated landforms in Chuckanut Formations

Acme Watershed

MWMU 1 (ARS MW-1)
- High or Moderate Convergent topography greater than or equal to 73%. Inner gorges, bedrock hollows, channel heads.



am/thps/nw/whatcom/aml/mwmusmall.aml



Map G-2

Slope Stability Sensitive Areas Lake Whatcom Landscape Planning Area Final Environmental Impact Statement




Potentially Unstable Slopes



December 08, 2003

/am/thps/nw/whatcom/aml/slopesmall.aml







December 09, 2003 A.Hitchcock /am/thps/nw/whatcom/aml/slopecombo.aml

Slope Stability and Stream Classification Lake Whatcom Landscape Planning Area Final Environmental Impact Statement

Water Type Code

Type 1

Type 2

Type 3

Type 4

Type 5

Wetlands and Swamps

Ponds and Lakes

MWMU 1B (ARS 1) - Moderate Headscarps and toes of ancient and dormant deep-seated landslides

MWMU 1C (ARS 2) - High Incised stream channels within deep-seated landslides

MWMU 2 (ARS 3) - High Incised stream channels and associated landforms in Darrington Phyllite


MWMU 4 (ARS 4) - High Incised stream channels and associated landforms in Chuckanut Formations

MWMU I (ARS MW-I)

- High or Moderate
Convergent topography greater than
or equal to 73%. Inner gorges,
bedrock hollows, channel heads.

Potentially Unstable Slopes





Lake Whatcom Landscape Plan Final Environmental Impact Statement Preferred Alternative

